

1 of 16



FIG. 1




FIG. 2

2 of 16




FIG. 3




FIG. 4




FIG. 5




FIG. 6

5 of 16

0	1	5	6	14	15	27	28
2	4	7	13	16	26	29	42
3	8	12	17	25	30	41	43
9	11	18	24	31	40	44	53
10	19	23	32	39	45	52	54
20	22	33	38	46	51	55	60
21	34	37	47	50	56	59	61
35	36	48	49	57	58	62	63

(A)

0	4	6	20	22	36	38	52
1	5	7	21	23	37	39	53
2	8	19	24	34	40	50	54
3	9	18	25	35	41	51	55
10	17	26	30	42	46	56	60
11	16	27	31	43	47	57	61
12	15	28	32	44	48	58	62
13	14	29	33	45	49	59	63

(B)

0	1	2	3	10	11	12	13
4	5	8	9	17	16	15	14
6	7	19	18	26	27	28	29
20	21	24	25	30	31	32	33
22	23	34	35	42	43	44	45
36	37	40	41	46	47	48	49
38	39	50	51	56	57	58	59
52	33	54	55	60	61	62	63

(C)

FIG. 7

X11	X12	X13	X14	X15	X16
X21	X22	0	0	0	
X31	0	0	0		
X41	0	0			
X51	X52				
X61					
X71					

(C)

0	1	5	12	6	11
2	4				
3	7				
8	10				
9	13				
14					
15					

(D)

X11	X12	X13	X14	X15	X16
X21	X22	0	0	0	0
X31	X32	0	0	0	0
X41	X42	0	0	0	0
X51	X52	0	0	0	0
X61	0	0	0	0	0
X71	0	0	0	0	0
0	0	0	0	0	0

(A)

X11	X12	X13	X14	X15	X16
X21	X22	0	0	0	
X31	X32	0	0		
X41	X42	0			
X51	X52				
X61					
X71					

(B)

X11	X12	X13	X14	X15	X16
X21	X22				
X31	0				
X41	0				
X51	X52				
X61					
X71					

(E)

FIG. 8




FIG. 9



FIG. 10






FIG. 11




FIG. 12a




FIG. 12b




FIG. 13




FIG. 14




FIG. 15




FIG. 16a




FIG. 16b